



POTENTIAL HAZARDOUS WASTE SITE
SITE IDENTIFICATION

I. IDENTIFICATION

01 STATE 02 SITE NUMBER
IA Unassigned

II. SITE NAME AND LOCATION

01 SITE NAME (Legal, common, or descriptive name of site)

Cedar Falls FMGP

02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER

Open lot west of 612 E. 12th Street

03 CITY

Cedar Falls

04 STATE

IA

05 ZIP CODE

50613

06 COUNTY

Black Hawk

07 COUNTY CODE

08 CONG DIST

09 DIRECTIONS TO SITE (Starting from nearest public road):

East of Main Street on 12th Street to open lot west of and adjacent to the existing power plant at 612 E. 12th Street.

Site: Cedar Falls
ID #: IAD98457117
Break: 6.4
Other: _____

III. RESPONSIBLE PARTIES

01 OWNER (if known)

Cedar Falls Utility Co.

02 STREET (Business, residential, mailing)

612 E. 12th Street

03 CITY

Cedar Falls

04 STATE

IA

05 ZIP CODE

50613

06 TELEPHONE NUMBER

(319) 266-1761

07 OPERATOR (if known and different from owner)

08 STREET (Business, residential, mailing)

09 CITY

10 STATE

11 ZIP CODE

12 TELEPHONE NUMBER

()

13 TYPE OF OWNERSHIP (Check one)

☐ A. PRIVATE

☐ B. FEDERAL

(Agency name)

☐ C. STATE

☐ D. COUNTY

☐ E. MUNICIPAL

☐ F. OTHER

(Specify)

☐ G. UNKNOWN

IV. HOW IDENTIFIED

01 DATE IDENTIFIED

0322, 90

MONTH DAY YEAR

02 IDENTIFIED BY (Check all that apply)

☐ A. CITIZEN COMPLAINT

☐ B. INDUSTRY

☐ C. STATE/LOCAL GOVERNMENT

☐ D. AERIAL RECONNAISSANCE

☐ E. RCRA INSPECTION

☐ F. SURFACE IMPOUNDMENT ASSESSMENT

☒ G. OTHER EPA IDENTIFICATION

☐ H. OTHER

(Specify)

V. SITE CHARACTERIZATION

01 TYPE OF SITE (Check all that apply)

☐ A. STORAGE

☐ B. TREATMENT

☐ C. DISPOSAL

☐ D. UNAUTHORIZED DUMPING

☒ E. OTHER FMGP

(Specify)

02 SUMMARY OF KNOWN PROBLEMS (Provide narrative description)

Problems associated with previously investigated FMGP's have been the presences of carcinogenic PAH's from tar wates and cyanides from purification wastes.

03 SUMMARY OF ALLEGED OR POTENTIAL PROBLEMS (Provide narrative description)

~~Problems associated with previously investigated FMGP's have been the presences of~~
Potential problems may exist through the contamination, by PAH's and cyanides, of the soil, air, groundwater, and surface water pathways.

VI. INFORMATION AVAILABLE FROM

01 CONTACT

Pete Culver, IA Coord.

02 OF (Agency/Organization)

EPA

03 TELEPHONE NUMBER

(319) 551-7707

04 PREPARED BY

Scott Hayes

05 AGENCY

Contractor

06 ORGANIZATION

E&E, Inc.

07 TELEPHONE NUMBER

(913) 432-9961

08 DATE

07, 19, 90

MONTH DAY YEAR

